



TechTool Pro 14 Release Notes

Version 14.0.4

1/19/2022

- Fixed eDrive tool to avoid a potential application crash during the partitioning stage.
- Fixed Fans Test and Battery Check animations to support the latest MacBook Pros.
- Fixed incorrect Battery manufacturer info in the Battery Check test.
- Fixed duplicate M1 Pro and M1 Max processor names in the Processor Check tool.
- Added support for MacBook Pro (14-inch, 2021) and MacBook Pro (16-inch, 2021) in the Sensors Test.
- Added a missing entry for MacBook Pro (16-inch, 2019) for the Sensors Test.
- Updated SAT SMART Driver Installer with latest code signing certificate.
- Updated Bonjour manufacturer database for the Local Network tool.
- Updated Sparkle framework to version 1.27.1.
- Added model identification strings for the Check Computer configuration panel.
- Other minor fixes and enhancements.

Version 14.0.3

10/13/2021

- Fixed issue in which new eDrive volumes would never successfully complete.
- Fixed eDrive to correctly remove HFS+ formatted eDrive volumes under macOS 11 Big Sur.
- Fixed eDrive and Protogo Basic profile to display correct startup volume icon under macOS 11 Big Sur.
- Updated the macOS Dock items for the Protogo Basic profile and eDrive under macOS 11 Big Sur.
- Added support for new iPhone and iPad models in the Battery Check test.
- Added 'Data' partition to eDrive and Protogo devices for macOS 11 Big Sur.
- Added a forced restart for first eDrive startup for macOS 11 Big Sur.
- Remove Power On Self-Test feature from TechTool Protection if no data is present.
- Updated the Bluetooth test to correctly state 'Off' for the Discoverable field.
- Updated Bonjour database file for the Local Network tool.
- Updated Sparkle to reference the correct version in the application.
- Added model identification strings for the Check Computer configuration panel.
- Other minor fixes and enhancements.

Version 14.0.2

7/13/2021

- Updated eDrive and TechTool Protogo to use APFS as the volume format for macOS Big Sur users.
- Additional support for iMac (24-inch, M1, 2021) in the Sensors Test and the Processor Check tool.
- Fixed Snapshot Recovery tool to operate as expected when booted from the eDrive.
- Fixed TechTool Protogo to prevent incorrectly displaying unmounted system volumes.

- Fixed the Snapshot Recovery search results window to resize correctly for macOS Big Sur users.
- Fixed Snapshot Recovery to correctly handle localized dates and date formatting.
- Added French, German and Japanese versions of the TechTool Pro 14 PDF manual.
- Added model identification strings for the Check Computer configuration panel.
- Other minor fixes and enhancements.

Version 14.0.1

4/30/2021

- Initial version.